

Belzona Saves Retirement Residence Over \$7,000



Shroud grit blasted



*Completed coating with
Belzona® 5111 (Ceramic Cladding)*

STATISTICS

CUSTOMER

Retirement residence,
Florida, USA

APPLICATION DATE

October 1993

SUBSTRATE

Sheet Steel

PRODUCTS

Belzona® 1111
Belzona® 6111
Belzona® 5111

APPLICATION SITUATION

Rooftop exhaust fan shroud.

PROBLEM

A six foot diameter exhaust fan is used in case of a fire to evacuate smoke from the burning building. The corroded metal shroud developed holes. Rainwater entered through the holes and caused water damage to the inside of the building.

APPLICATION METHOD

The application was carried out in accordance with a Belzona Know-How System Leaflets FBC-2 and -4.

BELZONA FACTS

The cost of a new stainless steel shroud was \$9600. The existing shroud was salvaged with approximately \$600 in products. Including blasting, the customer saved over \$7000.