

## Belzona Protects Mixing Tank



*Bare unprotected mixing tank*



*Surface prepared and holes patched with Belzona® 4111*



*First coat of Belzona® 5811 being applied*



*Final coat Belzona® 5811 applied*

### STATISTICS

#### CUSTOMER

Dairy,  
Oklahoma, USA

#### APPLICATION DATE

March 2006

#### SUBSTRATE

Concrete

#### PRODUCTS

Belzona® 4111  
Belzona® 5811

#### APPLICATION SITUATION

During expansion, the large dairy constructed a new water plant to treat their own water (average 400,000 GPD).

#### PROBLEM

Customer needed protection on their  $KMnO_4$  (Potassium Permanganate) mixing tank.

#### APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System leaflet TCC-15.

#### BELZONA FACTS

Customer choose Belzona based on success of previous applications.